

Four Seasons® introduces Motor Resistor Kits featuring a quality blower motor, blower motor resistor and high temp* harness connector in a single carton. These problem solving kits are application specific and help reduce warranty by providing all the electrical components that commonly fail together offering a proper replacement of both the motor and resistor for a successful, long lasting repair.



P/N 35334BRK1
VIO: 379,648
87-76 Buick
96-77 Chevrolet




P/N 35344BRK1
VIO: 303,189
05-96 Chevrolet Astro
05-96 GMC Safari




P/N 35344BRK2
VIO: 1.4 M+
05-95 Chevrolet S10 Blazer
01-96 Oldsmobile Bravada



P/N 35344BRK3
VIO: 111,495
92-89 Chevrolet Camaro
94 GMC S15 Pickup




P/N 75712BRK1
VIO: 622,168
01-97 Jeep Cherokee
01-97 Jeep Wrangler




P/N 75735BRK1
VIO: 906,004
08-04 Acura TSX
05-03 Honda Accord

For complete application information, visit the ecatalog at www.4s.com.

High O.E. Failure Rate



P/N 75740BRK1
VIO: 478,106
04-01 Dodge Dakota
03-01 Dodge Durango



75744BRK1
VIO: 611,258
12-04 Chevrolet Colorado
12-4 GMC Canyon



P/N 75748BRK1
VIO: 4.5 M+
06-03 Cadillac Escalade
06-03 GMC Fullsize Pickup



P/N 75748BRK2
VIO: 1 M+
09-07 Cadillac Escalade
09-07 GMC Fullsize Pickup



P/N 75748BRK3
VIO: 5.1 M+
06-03 Cadillac Escalade w/o Rear Air
07-03 GMC Full Size Pickup w/o Console



P/N 75748BRK4
VIO: 5.1 M+
06-03 Cadillac Escalade w/Rear Air
07-03 GMC Full Size Pickup w/Console

High O.E. Failure Rate



P/N 75835BRK1
VIO: 301,125
09-07 Chrysler Aspen
09-04 Dodge Durango



75852BRK1
VIO: 317,491
11-05 Ford Crown Victoria
11-05 Mercury Grand Marquis



P/N 75886BRK1
VIO: 3.9 M+
06-03 Chevrolet Avalance
07-03 GMC Full Size Pickup